

# Final Reclamation and Stormwater Inspection

July 18, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 320364

Well Name: DREYER #1

Inspection Document #: 718600796

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DREYER #1  
Location ID: 320364



**Photo 1.** Looking north across the tank battery. No oil and gas equipment remains. Desirable perennial vegetation appears to have reached 80% coverage of the reference area.



**Photo 2.** Looking south across the tank batter from the north side. See photo 1 comments.



Inspection Photos  
Location Name: DREYER #1  
Location ID: 320364



**Photo 3.** Looking north down the former access road. Desirable perennial vegetation on the access road appears to have reached 80% coverage of the reference area.



**Photo 4.** Looking north from the wellbore. No oil and gas equipment remains. Desirable perennial vegetation on the access road appears to have reached 80% coverage of the reference area.

Inspection Photos  
Location Name: DREYER #1  
Location ID: 320364



**Photo 5.** Looking west from the center of the location. See photo 4 comments.



**Photo 6.** Looking south from the center of the location. See photo 4 comments.

Inspection Photos  
Location Name: DREYER #1  
Location ID: 320364



**Photo 7.** Looking east from the center of the location. See photo 4 comments.



**Photo 8.** Reference vegetation to the east of the location. Reference vegetation is poor, primarily cheatgrass.

