

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

07/21/2025

Document Number:

707604090

**FIELD INSPECTION FORM**

Loc ID 306393 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_ecmc_engineering@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288466	WELL	SI	01/01/2025	OW	123-24576	FAULKNER 30-44	TA

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (306393).  
(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery / Facility Inspections):  
A.) Field Inspection Report doc. #707604090 and/or Location ID #306393 for TA Well(s) info.  
B.) Field Inspection Report doc. #707604092 and/or Location ID #306393 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment: OOSLAT tag applied at well flowline.		
Corrective Action:			Date:
	Type CONTAINERS		
	Comment: Wellsite(s): Propane. CORRECTIVE GUIDANCE COMMENT: 1.) Propane tank needs updated contents, capacity, & NFPA hazard labeling. Refer to Rule 605.h for guidance. Comply w/ Rule 605.h. See photo(s) #3.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
	Comment: Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
	Type WEEDS		
	Comment: CORRECTIVE GUIDANCE Item(s): 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. See photo(s) #1, 2, 3.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Pump Jack	# 1		corrective date

Comment:	Hydraulic pump jack. Tower removed from well. Hydraulic pump components; Surrounded by protective shed. Inactive   Shut-down. Disconnected from well. Rods, tubing pulled. Stacked neatly at wellsite.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine drives pump jack. Inactive   Shut-down. Surrounded by protective shed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.536901,-104.590226
Comment:	Centralized Battery serves 1 Location ID (306393). (Well(s): 1: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 288466 Type: WELL API Number: 123-24576 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT applied at well, separator.  
ECMC records last production: 12/2024.  
  
Rods, Tbg pulled; 12/2024.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On WED 07/16/2025 at approximately 14:22 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: FAULKNER-67N64W/30SESE                      Location ID: 306393                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report.                      Location County: Weld County, Colorado                      Weather: Mostly Cloudy, dry.</p> <p>While there, I observed:                      Well(s): 1:Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p><b>**CORRECTIVE GUIDANCE COMMENT(s):</b>                      1. Refer to pg 2, Signs / Marker section.                      2. Refer to pg 2, Good Housekeeping section.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	07/21/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707604091	Inspection photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152760">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7152760</a>