

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

07/16/2025

Document Number:

716301240

FIELD INSPECTION FORM

Loc ID 333911 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
,		dnr_ecmc_engineering@state.co.us	
B WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276686	WELL	TA	10/08/2013	GW	071-08350	NEW ELK 36-11 CH	PA
276687	WELL	PR	02/18/2005	CBM	071-08351	NEW ELK 36-11	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Ancillary equipment	# 2				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Pump Jack	# 1				
		Comment: NE 36-11 WELL			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Other	# 1				
		Comment: 25 BBLs PRODUCED WATER TANK			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Vertical Separator	# 2				
		Comment: <input type="text"/>			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Gas Meter Run	# 2				
		Comment: BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Bradenhead	# 2				
		Comment: BOTH ARE ACCESSABLE			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Prime Mover	# 1				
		Comment: NE 36-11 WELL			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Other	# 1				
		Comment: 15 BBL PRODUCED WATER TANK			
			Corrective Action: <input type="text"/>	Date: <input type="text"/>	
Type: Deadman # & Marked	# 6				
		Comment: <input type="text"/>			

Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	NE 36-11 WELL		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 276686 Type: WELL API Number: 071-08350 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL IS PA, WELL WAS 2 YEARS PAST DUE FOR 5 YEAR MIT

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276687 Type: WELL API Number: 071-08351 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/04/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 292667 Lat: 37.126030 Long: -104.949600

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301241	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7153239