



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Ancillary equipment		# 1		
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:
Type: Other		# 1		
Comment:	30 BBL PRODUCED WATER TANK			
Corrective Action:	<input type="text"/>			Date:
Type: Vertical Separator		# 1		
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:
Type: Prime Mover		# 1		
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:
Type: Pump Jack		# 1		
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:
Type: Compressor		# 1		
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:
Type: Bradenhead		# 1		
Comment:	IS ACCESSABLE			
Corrective Action:	<input type="text"/>			Date:
Type: Gas Meter Run		# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:	<input type="text"/>			Date:
Type: Deadman # & Marked		# 4		
Comment:	<input type="text"/>			

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 279154 Type: WELL API Number: 071-08469 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: YES      Pit ID: 292634      Lat: 37.132310      Long: -104.958200

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: YES      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301245	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7153241">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7153241</a>