

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2025

Submitted Date:

07/22/2025

Document Number:

698707766

FIELD INSPECTION FORM

Loc ID 309391 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------|---------|
| , Ogris | 719-220-4041 | gzeches@ogrisop.com | |
| Baca, Dave | 719-846-4066 | dbaca@ogrisop.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 294300 | WELL | PR | 07/01/2023 | CBM | 071-09474 | NEW ELK 25-02 | PR |

General Comment:

[Routine Inspection](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--------------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Well sign on meter house | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | Conduct maintenance on equipment, cleanup stained material and review self inspection processes. | | |
| Corrective Action: | COMPLY WITH RULE 1002.,(2).D | Date: | 07/29/2025 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type: | | # | | corrective date |
|--------------------|---|-----|-------|-----------------|
| Bradenhead | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Vertical Separator | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Bradenhead | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Progressive Cavity | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Gas Meter Run | | # 1 | | |
| Comment: | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | | |
| Corrective Action: | | | Date: | |
| Prime Mover | | # 1 | | |

| | | | |
|--------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | OTHER | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 25 bbl | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | |
| | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 294300 Type: WELL API Number: 071-09474 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Ditches | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

| | | | |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
| | 296581 | 2017102 | |

ECMC Comments

| | | |
|------------------------------------|--------|------------|
| Comment | User | Date |
| Routine Inspection | sernaa | 07/22/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 698707767 | Photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7154492 |