

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3529 From entrance to location



Photo # 3530 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3531 Location



Photo # 3532 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711




Photo # 3533 Location



Photo # 3534 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3535 Location



Photo # 3536 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3391 From inspection 708905234 conducted on 12/12/2024 Methanol tank improperly labeled/missing some required information



Photo # 3537 Methanol tank improperly labeled/missing some required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3392 From inspection 708905234 conducted on 12/12/2024 Methanol tank improperly labeled/missing some required information



Photo # 3538 Methanol tank improperly labeled/missing some required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711




Photo # 3539 Methanol tank improperly labeled/missing some required information

Photo # 3540 Methanol tank improperly labeled/missing some required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3541 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 3542 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3543 Debris



Photo # 3544 Pneumatic control valve on Summit Midstream pipeline has been modified/valve no longer has the ability to close

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad

Location ID: 334711



Photo # 3546 Pneumatic control valve on Summit Midstream pipeline has been modified/valve no longer has the ability to close



Photo # 3547 Supply gas line for Summit Midstream control valve disconnected/valve no longer operable