

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/16/2025

Document Number:

719000322**FIELD INSPECTION FORM**Loc ID 320886 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69805Name of Operator: PETROX RESOURCES INCAddress: 12600 W COLFAX AVENUE #C-440City: LAKEWOOD State: CO Zip: 80215**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Ryan		ryan@petrox-resources.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystwr@yahoo.com	All Inspections
Clark, Mike	970-878-5594	mike.petrox@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277656	WELL	PR	01/01/2023	CBM	007-06213	FOSSET GULCH UNIT 9U 2	PR

General Comment:

Inspection Report Summary
 On 7/15/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: FOSSET GULCH UNIT 9U 2
 Operator: PETROX RESOURCES
 API#: 007-06213
 County: ARCHULETA

ALL PRIOR CA'S STILL STAND

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	505-330-1328 303-803-3998 911 EMERGENCY		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	OVERGROWN VEGETATION ON EAST SIDE OF SEPARATOR AND ON LOCATION SEE LOCATION PICTURES		
Corrective Action:	CUT AND REMOVE per rule 606	Date:	07/30/2025

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	# 1		
Comment:	1 IN FLOW LINE ON EAST SIDE OF PUMP JACK WITH BULL PLUG SEE LOCATION PICTURES		
Corrective Action:	IF OUT OF SERVICE MUST BE LOCKED OUT AND TAGED OUT		Date: 07/30/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277656	Type:	WELL	API Number:	007-06213	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/17/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits:

☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
	garciacr1	07/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404282782	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7145384
719000333	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7145381