

3/23/73.

10/27/72

Field inspection -

#1 Qualls

Pits open, location not
leveled, casing (8 7/8") 3'
above surface, welded
plate & nipple at top,
then bull plug in nipple.
Bull plug leaking water,
pits full of water (foxhills)
water taste good, old rusty
pipe (10-15 joints) on
locations (5 1/2 - 6")

No Bond release!

Forms 4 & 5 received Jim
on 11/3/72

Jim

Laura - of Globe
Drilling called at
3:30 PM:

She said that John
Gable told her to call us
to let us know that
a 100 sfg cement plug was
placed in the Qualls well
and that it was too muddy
to fill and level pits at this
time; however I told her
to get the plugging report
into us Monday giving
us exact location and
how much cement was
used in plugging the well.

Also the Knute well
(over)

