

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404290802

Date Received:

07/23/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708302377

Inspection Date: 06/27/2024

FIR Submit Date: 07/03/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 335996

Location Name: AP-66S95W

Number: 18NENW

County: \_\_\_\_\_

Qtrqtr: NENW Sec: 18 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.529548 Longitude: -108.042274

### FACILITY - API Number: 05-045-

-00

Facility ID: 335996

Facility Name: AP-66S95W

Number: 18NENW

Qtrqtr: NENW Sec: 18 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.529548 Longitude: -108.042274

### CORRECTIVE ACTIONS:

1 CA# 196502

Corrective Action: Secure tank load line to comply with Rule 608.e.

Date: 07/08/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Open ended load lines have been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 196503

Corrective Action: Remove debris from location to comply with Rule 606.

Date: 07/08/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator  
Comment: Debris has been removed from the location. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

3 CA# 196504

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 07/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator  
Comment: Access road has been bladed/graded to address rills and to improve stormwater conveyance to the roadside ditch. Other rills and degradation have also been repaired. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #196502: Open ended load lines have been plugged. Corrective Action complete.  
CA #196503: Debris has been removed from the location. Corrective Action complete.  
CA #196504: Access road has been bladed/graded to address rills and to improve stormwater conveyance to the roadside ditch. Other rills and degradation have also been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 7/23/2025 10:59:31 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404290802	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files