

Federal Albatross 33-12/Federal Falcon 33-6  
15-Jul-25 15:10:31  
ECMC Environmental Inspection

Signage at Federal Falcon #33-06 tank battery (Location ID 467686)  
Weeds



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:10:47  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
Two (2) 300-bbl steel crude oil aboveground storage tanks (ASTs)  
Shared earthen secondary containment berm has started to erode  
Fencing adequate



Federal Falcon #33-06 tank battery (Location ID 467686)  
Meter shed, vertical heater treater, ECD - Fencing adequate  
Weeds

WGS84 40.62581, -104.10231  $\Delta$  m 1519  $\Delta$  °, T  $\pm$ 10 E77  
 $\pm$ 18ft  $\pm$ 5m



Occupied  
bird nest

Inadequate secondary  
containment around  
perimeter

**ECMC**  
**Environmental**  
**Field Inspection**




Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:12:24  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
Occupied bird nest in vertical heater treater firetube intake  
Inadequate secondary containment surrounding vertical heater treater




Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:12:58  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
50-bbl partially buried fiberglass skim tank and earthen pit.  
Adequate fencing.  
Earthen secondary containment berms are showing signs of erosion.  
Weeds.



Federal Albatross 33-12/Federal Falcon 33-6  
15-Jul-25 15:13:22  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
50-bbl partially buried fiberglass skim tank and earthen pit.  
Adequate fencing.  
Wildlife netting installed.  
Earthen secondary containment berms are showing signs of erosion (formation of rills).  
Weeds observed within/around the earthen pit and berm.



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:13:42  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
50-bbl partially buried fiberglass skim tank and earthen pit.  
Adequate fencing.  
Wildlife netting installed.  
Earthen secondary containment berms are showing signs of erosion.  
Weeds observed within/around the earthen pit and berm.  
Wind and stormwater have eroded sediment from the berms then transported and deposited the sediment (colluvium) along the perimeter and into the open pit.

WGS84  
±16ft


40.62590, -104.10209

m  
±4m

1519

°T  
±12

W263



Inadequate secondary  
containment around  
vertical heater treater

**ECMC**  
**Environmental**  
**Field Inspection**



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:13:56  
ECMC Environmental Inspection

Federal Falcon #33-06 tank battery (Location ID 467686)  
Meter shed, vertical heater treater, ECD - Fencing adequate.  
Inadequate secondary containment around vertical heater treater.

WGS84  $\pm 12\text{ft}$  40.62117, -104.09972  $\pm 3\text{m}$  1517  $\pm 13$  SE155



**ECMC**  
**Environmental**  
**Field Inspection**



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul 25 15:16:26  
ECMC Environmental Inspection

Signage at Federal Falcon #33-06 Well (API 123-20233)

WGS84 ±16ft 40.62109, -104.09974 m ±4m 1517 T ±10 SW201




**ECMC**  
**Environmental**  
**Field Inspection**



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:16:49  
ECMC Environmental Inspection

Stained soil beneath pumping unit at Federal Falcon #33-06 Well (API 123-20233)

WGS84  $\pm 7\text{ft}$  40.62110, -104.09973  $\wedge$   $\pm 3\text{m}$  1518  $\triangle$   $\pm 10$  °,T SW209




**ECMC**  
**Environmental**  
**Field Inspection**



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:17:00  
ECMC Environmental Inspection

Stained soil beneath pumping unit at Federal Falcon #33-06 Well (API 123-20233)

WGS84  $\pm 8\text{ft}$  40.62099, -104.09971  $\Delta$   $\pm 3\text{m}$  1517  $\text{m}$   $\pm 10$   $^{\circ}, \text{T}$  SE159



**ECMC**  
**Environmental**  
**Field Inspection**



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:17:17  
ECMC Environmental Inspection

Stained soil adjacent to pumping unit at Federal Falcon #33-06 Well (API 123-20233)

WGS84  $\pm 12\text{ft}$  40.62106, -104.09960  $\pm 3\text{m}$  1515  $\pm 10$  °,T N347




**ECMC**  
**Environmental**  
**Field Inspection**




Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:17:57  
ECMC Environmental Inspection

Stained soil adjacent to pumping unit at Federal Falcon #33-06 Well (API 123-20233)



Stained soil adjacent to pumping unit at Federal Albatross #33-12 Well (API 123-20232)  
Signage inadequate - Missing API and Operator Emergency Contact info.



Stained soil adjacent to pumping unit at Federal Albatross #33-12 Well (API 123-20232)

WGS84  
±7ft

40.61814, -104.10256

m  
±3m

1513

°T  
±10

SE161



Federal Albatross 33-12/Federal Falcon 33-6  
© 15-Jul-25 15:21:33  
ECMC Environmental Inspection

Stained soil adjacent to pumping unit at Federal Albatross #33-12 Well (API 123-20232)