

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2025

Submitted Date:

07/17/2025

Document Number:

708906873

**FIELD INSPECTION FORM**

Loc ID 322405 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210423	WELL	PR	10/01/1993	GW	045-06179	CLOUGH 101	PR

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)  
 On 07/15/2025 at approximately 11:02 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CLOUGH 101 Pad. Location # 322405 in Garfield County Colorado. Location is within High Priority/Density Habitat areas & in close proximity to Bald Eagle Roost Site. While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Inspected Facilities - CLOUGH 101 well lacks wellbore diagram with a CA date of 08/16/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection/audit report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Meter house Sign weathered but legible		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Meter house - hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Air compressor - hog panels		

Corrective Action:		Date:
<b>Equipment:</b>		corrective date
Type: Plunger Lift	# 0	
Comment: Well not on plunger lift		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment: Marked		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Taylor plug located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Air compressor		
Corrective Action:		Date:
<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:
<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 210423 Type: WELL API Number: 045-06179 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well not on plunger lift

Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

Date: 08/16/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Rip Rap				
		Ditches				
		Check Dams				
Compaction						Small amount of light compaction
Gravel						None
		Compaction				
		Gravel				Sparse to none in sections

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Inspected Facilities for corrective action &amp; also refer to Housekeeping for comments.</a>	smelserw	07/17/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404283326	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146110">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146110</a>
708906874	Inspection/Audit 708906873 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146104">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146104</a>
708906875	Inspection/Audit 708906873 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146105">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146105</a>