


**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



Top of 300 bbl tank is damaged. The top of the tank is rust through at the dumpline inlet. The open holes allow venting of the tank.

**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



There is a shutin riser behind the separator of GMR 27-4 and the OOSLAT tag is broken and needs replaced.

**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



2" dumpline is disconnected behind the separator for GMR 28-1A. No OOSLAT is on the line.



2" dumpline is disconnected behind the separator for GMR 28-1A. No OOSLAT is on the line.

**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



2" dumpline is disconnected behind the separator for GMR 28-1A. No OOSLAT is on the line.

**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**



**QB ENERGY OPERATING LLC
GMR-66S93W 27NWNW (D27NW)
Facility # 335326**

