

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2025

Submitted Date:

07/18/2025

Document Number:

707801705**FIELD INSPECTION FORM**Loc ID 313288 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments8 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
General, contact		argaliexplorationcompany@g mail.com	all inspections
,		dnr_cogccenforcement@state .co.us	Enforcement
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284611	WELL	SI	03/10/2015	GW	081-07302	SIMPSON 24-11	SI

General Comment:**ECMC Inspection Report Summary**

On Monday 8/19/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Simpson 24-11, at Location # 424711 in Moffat county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well appears to be bypassing the separator and selling strait from the casing to the sales line and not metered.

This location is within or in close proximity to a CPW Density/High Priority Habitat.

During this inspection the following possible compliance issues were observed:

1. Stored equipment.
2. Random debris
3. Well is selling from casing and not metered.
4. Emergency contact number is no longer a employee of Argali.
5. Signage at well and on location lack information.
6. Braden head is open to atmosphere.
7. Well is overdue for MIT if indeed shut in. All valves are open on casing and sales lines.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Location signage lacks proper information		
Corrective Action:	Provide proper signage	Date:	07/25/2025
Type	WELLHEAD		
Comment:	Well sign lacks proper information		
Corrective Action:	Provide proper signage	Date:	07/25/2025

Emergency Contact Number:

Comment: 970-629-1906/ Emergency contact number is no longer a employee of Argali.

Corrective Action: Provide proper signage for emergency contact

Date: 07/25/2025

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored equipment		
Corrective Action:	Remove stored equipment, put into service or provide proper documentation to keep on location.	Date:	08/08/2025
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/01/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Not in service		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Braden head is open to atmosphere. No evidence of valve in place to be able to close it.		
Corrective Action:	The Operator will equip Bradenhead access on all Wells to the Annulus between the production and surface casing as well as any intermediate casing with appropriate fittings to allow safe and convenient determination of pressure and Fluid flow	Date:	08/01/2025
Type: Gas Meter Run	# 0		
Comment:	No gas meter on location. Well appears to be bypassing the separator and selling strait from the casing to the sales line and not metered.		
Corrective Action:	Contact NW engineering. Provide proper measurement recordings.	Date:	07/21/2025
Type: Other	# 1		
Comment:	Well head		

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank on ground not contained		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No			
Comment:	Braden head is open to atmosphere.		
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	284611	Type:	WELL	API Number:	081-07302	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		Well is overdue for MIT if indeed shut in. All valves are open on casing and sales lines.								
Corrective Action:		A mechanical integrity test will be performed on each Shut-in Well within 2 years of the initial shut-in date. Subsequently, a mechanical integrity test will be performed on each Shut-in Well on 5-year intervals from the date the initial mechanical integrity test was performed, as long as the Well remains shut-in.						Date:		08/01/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: No BMP's installed to prevent sediment migration from occurring on location.						Date: _____
Corrective Action:						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404286018	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148769
707801706	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148754