

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2025

Submitted Date:

07/18/2025

Document Number:

715202656**FIELD INSPECTION FORM**Loc ID 321672 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77069**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207730	WELL	TA	03/30/2020	OW	017-06665	ARAPAHOE UNIT 147 (14-22)	PA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a Follow up Inspection from the P&amp;A process

Operator has plugged 10 wells in Cheyenne county including; AU 101, AU 121, AU 131, AU 133, AU 147, AU 155, AU 178, AU 180, Ashley 23-28, Rhoades 13-35

Due to the volume of wells plugged, the field inspector is granting a 30 day extension on removing equipment from locations with pumping units

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 0		
Comment:	Removed from inventory and moved to the AU 148		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Lufkin unit		
Corrective Action:	Remove equipment from location and begin final reclamation process		Date: 09/17/2025
Type: Vertical Heater Treater	# 0		
Comment:	Removed from inventory and moved to the AU 148		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed from unit		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:	Remove equipment from location and begin final reclamation process		Date: 09/17/2025
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment and cathodic rectifier		
Corrective Action:	Remove equipment from location and begin final reclamation process		Date: 09/17/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0	300 BBLs	STEEL AST		38.814280,-102.107260	
Comment: <a href="#">Removed from AU 147 inventory and added to AU 148</a>						
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0	300 BBLs	FIBERGLASS AST		38.814280,-102.107260	
Comment: <a href="#">Removed from AU 147 inventory and added to AU 148</a>						
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	207730	Type:	WELL	API Number:	017-06665	Status:	TA	Insp. Status:	PA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <span>Well has been plugged</span>									
Corrective Action: <span>Cut, cap and cover wellhead. Continue with final reclamation process in accordance with the Final Reclamation 1004 series</span> Date: 09/17/2025									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404286449	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149294">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149294</a>
715202666	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149279">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149279</a>