

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2025

Submitted Date:

07/25/2025

Document Number:

718300052

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	
,		inspections@civiresources.com	<a href="#">All Inspections</a>
Evans, Jacob		jevans@civiresources.com	
Hamilton, Schuyler		shamilton@civiresources.com	<a href="#">Civitas Environmental</a>
Mitchem, Katelyn		katelyn.mitchem@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
311323	LOCATION	AC			-	Federal 63N65W 4NESE Multi Well Pad	EI
333180	LOCATION	CL			-	ARISTOCRAT ANGUS-63N65W 3NWSW	EI
473091	OFF-LOCATION FLOWLINE	AC	12/06/2024		-	ARISTOCRAT ANGUS 63N 65W 3SWSW MULTI WELL PAD	EI

**General Comment:**

On July 17th, 2025, ECMC Environmental Protection Specialist Laurel Anderson and ECMC DJ Basin Environmental Supervisor Nikki Graber met personnel from Tasman Geosciences Inc (Operator's contractor) on location to witness resampling of FL-B15@3' at 2, 3, and 4' bgs via hand auger for laboratory analysis of full Table 915-1 analysis in response to comments applied to denied Form 27 Doc #404071624 submitted under Remediation Project 28042. Prior to sampling contractor personnel went over the scope of work and site specific JSA/HASP with ECMC representatives. The previous sample location was located using a handheld Trimble GNSS, samples were collected in accordance with ECMC Rule 915.e.(2) Soil Sampling and Analysis Operator Guidance and immediately placed on ice until submitted to the laboratory under standard chain of custody.

In addition to witnessing soil sampling at FL-B15 for the Aristocrat Angus 13-3 Flowline (Spill ID 484534/REM 28042)/Wellhead Line MULTI WELL PAD (Facility ID 473091), ECMC also evaluated final reclamation for the following locations:  
Federal 63N65W 4NESE Location (Location ID 311323)  
ARISTOCRAT ANGUS-63N65W Location (Location ID 333180) and associated access road

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. Photos attached to document site conditions.

Current site status:

-Weeds and bare soil observed throughout the final reclamation areas associated with:

Federal 63N65W 4NESE Location (Location ID 311323) - See Photos 1-3

ARISTOCRAT ANGUS-63N65W Location (Location ID 333180) - See Photos 5-7

Access road to Location ID 333180 - See Photo 4

Resampling of FL-B15 for the Aristocrat Angus 13-3 Flowline (Spill ID 484534/REM 28042)/Wellhead Line MULTI WELL PAD (Facility ID 473091) - See Photo 8

See attached corrective actions.

**Inspected Facilities**

Facility ID: 311323 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 333180 Type: LOCATION API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 473091 Type: OFF- API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: Remediation Project #28042 is associated with the decommissioning and abandonment of the Wellhead Line MULTI WELL PAD (Facility ID 473091) and site investigation and remediation of the Aristocrat Angus 13-3 Flowline spill (Spill ID 484534) in accordance with Rules: 913.c.(3) and 913.c.(9). Operator is past due on quarterly reporting. The last Supplemental Form 27 received (Doc #404071624) was submitted on 1/28/2025 and denied on 5/19/2025. The last approved Supplemental Form 27 (Doc #403978029) was submitted on 10/31/2024 and approved on 1/09/2025.

Corrective Action: Operator shall submit Quarterly Updates for this remediation project every 90 days as required by Rule 913.e. A replacement Supplemental Form 27 for Denied Form 27 Doc #404071624 was due upon denial of the form.

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Inspector Name: Anderson, Laurel

Corrective Action: <b>Comply with Rule 1004.e.</b>	Date <b>08/24/2025</b>	
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

**ECMC Comments**

Comment	User	Date
Inspector Comments: Weather: Overcast, no wind, ~65F PPE: Level D + FR	andersoln	07/25/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718300053	2025_0717_Aristocrat Angust Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7160908">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7160908</a>