

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2025

Submitted Date:

07/25/2025

Document Number:

719500262

FIELD INSPECTION FORM

Loc ID 335061 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280276	WELL	PR	02/13/2006	GW	045-11229	PUCKETT/TOSCO PA 41-35	PR
280287	WELL	PR	02/09/2006	GW	045-11232	PUCKETT/TOSCO PA 341-35	PR
288709	WELL	PR	01/04/2007	GW	045-13561	PUCKETT/TOSCO PA 42-35	PR
288710	WELL	PR	01/04/2007	GW	045-13560	PUCKETT/TOSCO PA 342-35	PR
288711	WELL	PR	01/04/2007	GW	045-13559	PUCKETT/TOSCO PA 541-35	PR
288713	WELL	PR	01/04/2007	GW	045-13558	PUCKETT/TOSCO RA 441-35	PR
288714	WELL	PR	01/04/2007	GW	045-13557	PUCKETT/TOSCO PA 444-26	PR
288715	WELL	PR	01/01/2019	GW	045-13556	PUCKETT/TOSCO PA 344-26	PR
288716	WELL	PR	01/04/2007	GW	045-13555	PUCKETT/TOSCO PA 44-26	PR
436787	WELL	PR	03/01/2022	GW	045-22370	Puckett Land Company PA 744-26	PR

General Comment:

CECMC Audit Report Summary

On 7/23/2025 at approximately 11:05, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, Puckett Land Company/PA 341-35 at Location ID #335061 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

1) Unserviceable tank label on storage tank

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Unserviceable tank label on storage tank.		
Corrective Action:	Comply with CECMC Signs and Markers rules.	Date:	08/26/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970)285-9377		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____
 Comment: _____
 Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280276	Type:	WELL	API Number:	045-11229	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	280287	Type:	WELL	API Number:	045-11232	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288709	Type:	WELL	API Number:	045-13561	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288710	Type:	WELL	API Number:	045-13560	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288711	Type:	WELL	API Number:	045-13559	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288713	Type:	WELL	API Number:	045-13558	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288714	Type:	WELL	API Number:	045-13557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	288715	Type:	WELL	API Number:	045-13556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:								Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288716 Type: WELL API Number: 045-13555 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436787 Type: WELL API Number: 045-22370 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				
		Culverts				
		Sediment Traps				
Rip Rap						
Compaction						
		Gravel				
		Check Dams				
Ditches						
		Rip Rap				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500263	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7162131