

**FORM  
INSP**

Rev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2025

Submitted Date:

07/29/2025

Document Number:

715801245

### FIELD INSPECTION FORM

Loc ID 318609 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241717	WELL	PR	09/01/2023	GW	123-09506	CHAMPLIN 86 AMOCO B 5	SI

**General Comment:**

[This is a wellsite file audit followed by a field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type			
Comment:	Tall vegetation growing around equipment & needs to be removed per Rule 606, 7 days to bring location into compliance. 8-5-2025		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type		#	corrective date
Prime Mover		# 1	
Comment:	electric motor		
Corrective Action:		Date:	
Bradenhead		# 1	
Comment:			
Corrective Action:		Date:	
Pump Jack		# 1	
Comment:			
Corrective Action:		Date:	
Ancillary equipment		# 1	
Comment:	Electric panel, meter box & transformers.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241717 Type: WELL API Number: 123-09506 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, electric panel is off, no meter on the meter box and valves are shut.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/10/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface, submit test results to the ECMC.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Tuesday 7-29-2025 at approximately 1357 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator: KP Kauffman                      Location # 318609                      API # 05-123-09506                      Well name: Champlin 86 Amoco B 5                      County: Weld                      Weather: Cloudy                      Temp: 82                      Location: dry                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      606 housekeeping: Tall vegetation growing around equipment.                      See attached photos.                      A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	07/29/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801246	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7166177">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7166177</a>