

Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328451

Inspection Document #: 718800588

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards as the location is dominated by weedy annual vegetation. At the time of this inspection, the location has been recently mowed.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the access road to the tank battery location, facing south. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation was observed across the location, including cheatgrass (*Bromus tectorum*).

Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 7. Photo taken of the access road to the location, facing northeast. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation was observed across the location, including cheatgrass (*Bromus tectorum*). At the time of this inspection, the location has been recently mowed.

Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 9. Photo taken of the tank battery location, facing southeast. See comments under Photo 8.



Photo 10. Photo taken of the tank battery location, facing south. See comments under Photo 8.



Inspection Photos
Location Name: DUNCAN D #20-2
Location ID: 328451



Photo 11. Photo taken of the reference area south of the location, facing east. Photo illustrates perennial grass vegetation.