

# Final Reclamation Inspection

July 10, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328767

Inspection Document #: 718800601

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates drill rows from seeding, bare ground, and weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*).



**Photo 6.** Photo taken of the access road to the location, facing southwest, towards the location. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.

Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 7.** Photo taken of the tank battery location, facing west. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and the site is dominated by weedy annual vegetation.



**Photo 8.** Photo taken of the tank battery location, facing southwest. See comments under Photo 7.



Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 9.** Photo taken of the tank battery location, facing east. See comments under Photo 7.



**Photo 10.** Photo taken of the tank battery location, facing northeast. See comments under Photo 7.



Inspection Photos  
Location Name: DUNCAN D #20-15  
Location ID: 328767



**Photo 11.** Photo taken of the reference area for the location, west of the location, facing northwest. Photo illustrates sand sagebrush (*Artemisia filifolia*) and prairie sunflower (*Helianthus petiolaris*).