

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2025

Submitted Date:

07/21/2025

Document Number:

707801710

FIELD INSPECTION FORM

Loc ID 450746 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 45898
Name of Operator: KAISER-FRANCIS OIL COMPANY
Address: P O BOX 21468
City: TULSA State: OK Zip: 74121

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Opfer, Christina	(918) 491-4468	christinao@kfoc.net	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450747	TANK BATTERY	AC	05/24/2017		-	32 8N90W Central Battery	AC

General Comment:

[ECMC Inspection Report Summary](#)
On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Kaiser Francis Gooch 2-33, at Location # 312777 in Route county Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
During this inspection the following possible compliance issues were observed:
1. Tank signage lacks information.
2. Chemical tanks need maintained.
3. No evidence of calibration cards on meters.

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tanks lack information		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: A. Name of Operator B. Operator's emergency contact telephone number C. Tank capacity D. Tank contents and E. NFPA label or equivalent globally harmonized label	Date:	<u>09/01/2025</u>
Emergency Contact Number:			
Comment:	(405) 262-5511		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 6		corrective date
Comment:	No evidence of calibration cards on meters.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.		Date: <u>08/15/2025</u>
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	500 gallon glycol tank in earth containment needs maintained.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Needs maintained shares containment with 500 gallon tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 450747 Type: TANK API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801725	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168080