

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2025

Submitted Date:

07/30/2025

Document Number:

719000390

## FIELD INSPECTION FORM

Loc ID 334262 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215009	WELL	PR	07/12/1984	CBM	067-06614	MAYFIELD B 1	PR
295623	WELL	PR	09/22/2008	CBM	067-09536	MAYFIELD B 3	PR
474313	Domestic Tap	AC	03/26/2020		-	Domestic Tap 10SWSE	AC

**General Comment:**

[Inspection Report Summary](#)  
On 07/30/25 | Inspector Charles Garcia  
conducted an on-site inspection.  
Location: MAYFIELD B1, B3  
Operator: Simcoe LLC  
API#: 067-06614  
API#: 067-09356  
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANLES		
Corrective Action:			Date:
Type	OTHER		
Comment:	PRODUCED WATER TANK METER HOUSES CATTLE PANLES		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line # 2			corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator # 2			
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment # 6			
Comment:	ELECTRIC PANLES		
Corrective Action:			Date:

Type: Other	# 1		
Comment:	DOMESTIC TAP		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.200900,-107.701000
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 215009 Type: WELL API Number: 067-06614 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 07/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 295623 Type: WELL API Number: 067-09536 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 07/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 474313 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000391	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168638">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168638</a>