

WGS84  $\pm 7\text{ft}$  39.99522, -103.83319  $\pm 3\text{m}$  1474  $\pm 10$  NE50



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:27:41 PM  
ECMC Environmental Inspection

Signage with emergency contact number is visible at the wellhead.

WGS84  $\pm 15\text{ft}$  39.99524, -103.83308  $\Delta$   $\pm 4\text{m}$  1474  $\triangle$   $\pm 10$  °,T N9



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:29:07 PM  
ECMC Environmental Inspection

A container (bucket, approximately 5 gallons) of unknown petroleum hydrocarbon fluid was visible adjacent to the wellhead.

WGS84 ±18ft 39.99526, -103.83308 m ±4m 1474 °, T ±10 N14



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:29:19 PM  
ECMC Environmental Inspection

WGS84  $\pm 18\text{ft}$  39.99524, -103.83309  $\wedge^m$   $\pm 4\text{m}$  1474  $\triangle^{\circ, T}$   $\pm 10$  SW229



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:29:25 PM  
ECMC Environmental Inspection

Additional unmarked containers (beige spill bucket, blue drum, white bucket) were visible on location and appear to have been splattered with petroleum hydrocarbon fluids. The bucket appears to contain unknown petroleum hydrocarbon fluid.

WGS84 39.99528, -103.83307 m 1474 °T NW299  
±19ft ±5m ±11



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:30:03 PM  
ECMC Environmental Inspection

Stained soil was visible adjacent to the wellhead. A petroleum hydrocarbon odor was observed when the stained soil was disturbed.

WGS84 39.99528 -103.83312 1475 °T ±18ft ±11 E98



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:30:16 PM  
ECMC Environmental Inspection

Stained soil was visible in multiple locations adjacent to the wellhead. Trash (black pieces of plastic) was visible.

WGS84  
±16ft

39.99529, -103.83314

m  
±4m

1475

°T  
±11

NE72



ECMC  
Environmental  
Field Inspection



Simpson #9  
© 13-Jun-25 03:30:39 PM  
ECMC Environmental Inspection

Pipes were visible adjacent to the wellhead.

WGS84  $\pm 13\text{ft}$  39.99526, -103.83320  $\wedge^m$   $\pm 3\text{m}$  1475  $\circ\text{T}$   $\pm 11$  S169



ECMC  
Environmental  
Field Inspection 

Simpson #9  
© 13-Jun-25 03:31:10 PM  
ECMC Environmental Inspection

An unmarked metal drum and unused equipment were visible adjacent to the wellhead.