

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2025

Submitted Date:

07/31/2025

Document Number:

701104225

**FIELD INSPECTION FORM**

Loc ID 335409 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275315	WELL	PR	06/01/2012	GW	045-13512	ALP (K19CNE) 24-9C	EG
423486	WELL	SI	09/01/2024	GW	045-20751	ENCANA FEE 24-1B (K19CNE)	EG
423488	WELL	PR	09/10/2013	GW	045-20753	ENCANA FEE 24-1A (K19CNE)	EG
423489	WELL	PR	07/30/2013	GW	045-20754	ENCANA FEE 24-8B2 (K19CNE)	EG
423491	WELL	PR	08/04/2013	GW	045-20756	ENCANA FEE 24-8C2 (K19CNE)	EG
423492	WELL	PR	01/01/2022	GW	045-20757	ENCANA FEE 19-13D (K19CNE)	EG
423493	WELL	PR	09/10/2013	GW	045-20758	ENCANA FEE 24-8C (K19CNE)	EG
423494	WELL	PR	07/30/2012	GW	045-20759	Encana Fee 19-6B (K19CNE)	EG
423495	WELL	PR	11/01/2023	GW	045-20760	ENCANA FEE 24-9B (K19CNE)	EG
423499	WELL	PR	06/01/2012	GW	045-20764	Encana Fee 19-11B (K19CNE)	EG
423501	WELL	PR	07/30/2012	GW	045-20766	Encana Fee 19-11D (K19CNE)	EG
423503	WELL	PR	09/10/2013	GW	045-20768	ENCANA FEE 24-8B1 (K19CNE)	EG
423504	WELL	PR	08/01/2018	GW	045-20769	Encana Fee 19-12D (K19CNE)	EG
423505	WELL	PR	08/10/2012	GW	045-20770	ENCANA FEE 19-5A2 (K19CNE)	EG

423506	WELL	PR	08/10/2012	GW	045-20771	Encana Fee 19-6D (K19CNE)	EG
423508	WELL	PR	05/17/2012	GW	045-20773	Encana Fee 19-13A (K19CNE)	EG
423511	WELL	PR	08/10/2012	GW	045-20776	Encana Fee 19-5A (K19CNE)	EG
423512	WELL	PR	07/30/2012	GW	045-20777	ENCANA FEE 19-10B (K19CNE)	EG
423573	WELL	PR	09/10/2013	GW	045-20778	ENCANA FEDERAL 24-10D (K19CNE)	EG

**General Comment:**

Flowline Integrity Inspection  
 Flowline abandonment  
 06/19/2025 Form 42 doc # 404247327  
 Form 44 doc # 403656139 Abandon in place 7817 - K19NE, 7816 - K19CNE  
 In process Form 44 doc# 404285147 comment "Lines 7817-K19NE and 7816 - K19CNE were abandoned in place as described in document 403656139 for numerous reasons. The pressure test and third-party verification data have been attached. All GIS will be submitted at our next quarterly update."  
 Multiple unused risers missing OOSLAT tags. Several of the risers have weathered broken tags.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Multiple unused risers missing OOSLAT tags. Several of the risers have weathered broken tags.		
Corrective Action:	Install or replace OOSLAT tags.	Date:	08/15/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	275315	Type:	WELL	API Number:	045-13512	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423486	Type:	WELL	API Number:	045-20751	Status:	SI	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423488	Type:	WELL	API Number:	045-20753	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423489	Type:	WELL	API Number:	045-20754	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423491	Type:	WELL	API Number:	045-20756	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423492	Type:	WELL	API Number:	045-20757	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423493	Type:	WELL	API Number:	045-20758	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423494	Type:	WELL	API Number:	045-20759	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423495	Type:	WELL	API Number:	045-20760	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423499	Type:	WELL	API Number:	045-20764	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423501	Type:	WELL	API Number:	045-20766	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423503	Type:	WELL	API Number:	045-20768	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423504	Type:	WELL	API Number:	045-20769	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423505	Type:	WELL	API Number:	045-20770	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423506	Type:	WELL	API Number:	045-20771	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	423508	Type:	WELL	API Number:	045-20773	Status:	PR	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Facility ID: 423511 Type: WELL API Number: 045-20776 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 423512 Type: WELL API Number: 045-20777 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 423573 Type: WELL API Number: 045-20778 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104226	Flowline integrity inspection 701104225 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170270">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170270</a>