

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2025

Submitted Date:

07/31/2025

Document Number:

707801728

**FIELD INSPECTION FORM**

Loc ID 312949 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		dnr_cogccengineering@state.co.us	<a href="#">engineering</a>
General, contact		argaliexplorationcompany@gmail.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222989	WELL	PR	02/01/2024	GW	081-06351	MC WILLIAMS 2-31	PR

**General Comment:**

ECMC Inspection Report Summary  
On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Exploration McWilliams 2-31, at Location # 312949 in Route county Colorado.  
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.  
During this inspection the following possible compliance issues were observed:  
1. Random debris  
2. Unused equipment (methanol tank)  
3. No form 15 on file for pit.

Refer to photograph of observed compliance issue.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused equipment (methanol tank)		
Corrective Action:	Remove unused equipment	Date:	09/01/2025
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/15/2025

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:			corrective date
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 222989 Type: WELL API Number: 081-06351 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. No form 15 on file for pit.  
No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908

Date: 08/21/2025

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water                  Lined: NO                  Pit ID:                  Lat:                  Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock                  Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801732	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170448">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170448</a>