

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2025

Submitted Date:

08/01/2025

Document Number:

715202722

**FIELD INSPECTION FORM**

Loc ID 303715 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253515      | WELL | PR     | 07/01/2015  | GW         | 125-07392 | ROSE 3-19     | PR          |

**General Comment:**

[SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment](#)

**Location**

|                    |                           |  |       |
|--------------------|---------------------------|--|-------|
| <b>Lease Road:</b> |                           |  |       |
| Type               | Access                    |  |       |
| comment:           | Two track through pasture |  |       |
| Corrective ActionL |                           |  | Date: |

Overall Good:

|                      |  |  |       |
|----------------------|--|--|-------|
| <b>Signs/Marker:</b> |  |  |       |
| Type                 | WELLHEAD   |  |       |
| Comment:             | Lease sign mounted to fence by wellhead and next to meter shed |  |       |
| Corrective Action:   |  |  | Date: |

|                                  |  |  |             |
|----------------------------------|--|--|-------------|
| <b>Emergency Contact Number:</b> |  |  |             |
| Comment:                         | <input style="width: 95%;" type="text"/> |  |             |
| Corrective Action:               | <input style="width: 95%;" type="text"/> |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Fencing/:</b>   |  |  |       |
| Type               | WELLHEAD                               |  |       |
| Comment:           | Metal panels around meter shed and VGS |  |       |
| Corrective Action: |  |  | Date: |

|                          |   |  |                 |
|--------------------------|---|--|-----------------|
| <b>Equipment:</b>        |   |  | corrective date |
| Type: Gas Meter Run      | # 1   |  |                 |
| Comment:                 | Meter shed on south side of wellhead            |  |                 |
| Corrective Action:       |   |  | Date:           |
| Type: Vertical Separator | # 1   |  |                 |
| Comment:                 | Vertical gas separator 50% buried by meter shed |  |                 |
| Corrective Action:       |   |  | Date:           |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Venting:</b>    |  |  |       |
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Flaring:</b>    |  |  |       |
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 253515 Type: WELL API Number: 125-07392 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: [Access has erosion and will need maintenance](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 715202748    | location photo | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7171834">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7171834</a> |