

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2025

Submitted Date:

08/03/2025

Document Number:

708907048

FIELD INSPECTION FORM

Loc ID 324141 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| TEP | | ECMCInspectionReports@flywheelenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 259119 | WELL | PR | 04/21/2001 | GW | 045-07687 | AMERICAN SODA GM 261-2 | PR |

General Comment:

[CECMC Inspection/Audit Report Summary](#)
On 07/31/2025 at approximately 15:28 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 261-2
Location # 324141 in Garfield County Colorado.
Location is within High Priority/Density/NSO/Black Bear Habitat areas.
Location is approximately 80 yards from Parachute Creek.
While there, I observed normal production operations.

This is a summary of inspection/audit report

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|--|--|-------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | No tank battery on location | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Sign weathered & cracking but still legible at this time | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911/970-285-9377 | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|-----------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Pipe rail fence | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|---|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Taylor plug located on bradenhead, bradenhead valve is accessible | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | Well on plunger lift | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 259119 Type: WELL API Number: 045-07687 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------------|
| | | Gravel | | | | Sparse to none in most sections |
| | | Compaction | | | | Small amount of light compaction |
| Gravel | | | | | | Sparse to none |
| | | Ditches | | | | |
| | | Culverts | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| Split pad/Remote location - Shared facilities with the UNOCAL GM 22-2 Pad location # 323962 | smelserw | 08/03/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 708907049 | Inspection/Audit 708907048 photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7172652 |
| 708907050 | Inspection/Audit 708907048 Stormwater photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7172653 |