

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2025

Submitted Date:

08/04/2025

Document Number:

707801735

FIELD INSPECTION FORM

 Loc ID 312982 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 3975
 Name of Operator: ARGALI EXPLORATION COMPANY
 Address: PO BOX 416
 City: RANGELY State: CO Zip: 81648
Findings:

- 16 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, COGCC		dnr_cogccengineering@state.co.us	engineering
General, contact		argaliexplorationcompany@gmail.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223159	WELL	PR	09/01/2018	GW	081-06521	MCWILLIAMS 4-31	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Exploration McWilliams 4-31, at Location # 312982 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Random debris
2. Weeds throughout location and access road.
3. Well head signage is illegible.
4. 1000 gallon methanol tank is unused equipment and not properly contained.
5. No form 15 on file for pit.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Well head signage is illegible.		
Corrective Action:	Within 60 days after a new Well is Completed, including each Well on a Multi-Well Site, or an existing sign is replaced or modified, a permanent sign will be conspicuously located at the wellhead and will identify: A. The Well name; B. The API number; and C. Its legal location, including the quarter/quarter section. When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: A. Name of the Operator; B. Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); and D. The public road used to access the Well.		Date: <u>09/04/2025</u>
Emergency Contact Number:			
Comment:	970-629-1906		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris.		Date: <u>09/04/2025</u>
Type	OTHER		
Comment:	No form 15 on file for pit.		
Corrective Action:	Provide proper documentation for open earth pit.		Date: <u>09/04/2025</u>
Type	UNUSED EQUIPMENT		
Comment:	1000 gallon methanol tank is unused equipment and not properly contained.		
Corrective Action:	Remove unused equipment or put into service and have proper secondary containment.		Date: <u>09/04/2025</u>
Type	WEEDS		
Comment:	Weeds throughout location and access road.		
Corrective Action:	Maintain lease road and location.		Date: <u>09/04/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			corrective date
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in metal containment		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Well head		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 223159 Type: WELL API Number: 081-06521 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement. No form 15 on file for pit.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: _____ Lat: _____ Long: _____
 Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:
 Liner Type: _____ Liner Condition: _____

Comment: None

Corrective Action Date: _____

Fencing:
 Fencing Type: Livestock Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____

Comment: None

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: None

Corrective Action Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801739	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174082