

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2025

Submitted Date:

08/04/2025

Document Number:

719000457

**FIELD INSPECTION FORM**

Loc ID 334174 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215096	WELL	PR	03/25/1984	CBM	067-06701	MAYFIELD 14U-01 1	PR
293810	WELL	PR	11/30/2007	CBM	067-09451	MAYFIELD 14U-01 3	PR

**General Comment:**

[Inspection Report Summary](#)  
On 08/04/25 | Inspector Charles Garcia conducted an on-site inspection.  
Location: MAYFIELD 14U-1 #1 , 14U -01 #3  
Operator: Simcoe LLC  
API#: 067-06701  
API#: 067-09451  
County: LaPlata

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK LABLE NEEDS REPLACED SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	09/04/2025

Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	CATTLE PANLES		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK TELEMETRY EQUIPMENT METER HOUSE		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	CATTLE PANLES		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	CATTLE PANLES		
Corrective Action:		Date:	

<b>Equipment:</b>			
Type: Other	# 2		corrective date
Comment:	WELLHEADS		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 4		
Comment:	ELECTRIC PANLES TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	ELECTRIC		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.196000,-107.691400
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215096 Type: WELL API Number: 067-06701 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 50%;" type="text"/>

**BradenHead**

Date of Last Brhd Test: 07/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293810 Type: WELL API Number: 067-09451 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<input style="width: 95%;" type="text"/>	
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 50%;" type="text"/>

**BradenHead**

Date of Last Brhd Test: 07/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000458	LOCATION PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174267">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174267</a>