

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2025

Submitted Date:

08/04/2025

Document Number:

707604133

**FIELD INSPECTION FORM**

Loc ID 419243 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438025	WELL	PR	12/01/2024	OW	123-39842	MOJACK N-28HC	PA

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Flowline valve remains at PA wellsite. Well has been cut/cap'd.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 438025 Type: WELL API Number: 123-39842 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On THU 07/31/2025 at approximately 14:31 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: Mojack/28-C Pad                      Location ID: 419243                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report. and/or photo(s) #1 attached to this report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Battery: Active.                      Active Battery SE corner GPS coordinates: 40.550327 / -104.550183</p> <p><b>WELL STATUS COMMENT:</b>                      Plugged &amp; Abandoned   PA.                      Form 6-SRA NOT on file. Surface plug date: 05/01/2025.                      Cut/cap'd date: 07/07/2025. Per Chevron records.                      Plugged &amp; Abandoned   PA well GPS coordinates: 40.550684 / -104.551367</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/04/2025

<p>This is a PLUGGED &amp; ABANDONED WELL inspection.                  Well(s): 1: Plugged &amp; Abandoned   PA.                  Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (419243).                  (Well(s): 7: Producing   PR; 1: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (425992).</p> <p>Reference (Associated Well(s), Battery Inspections):                  A.) Field Inspection Report doc. #707604131 and/or Location ID #419243 for PR Well(s) info.                  B.) Field Inspection Report doc. #707604133 and/or Location ID #419243 for PA Well(s) info.                  C.) Field Inspection Report doc. #707604135 and/or Facility ID #425992 for Battery / Facility, Equipment info.</p>	<p>evinsb</p>	<p>08/04/2025</p>
---	---------------	-------------------

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707604134	Photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174389">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7174389</a>