

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2025

Submitted Date:

07/29/2025

Document Number:

715202710

**FIELD INSPECTION FORM**

Loc ID 321951 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 59925  
Name of Operator: MONUMENT GAS MARKETING INC  
Address: P O BOX 950  
City: MONUMENT State: CO Zip: 80132-

**Findings:**

- 16 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Campbell, Randy	(719) 481-8029	rcampbell0614@adelphia.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274906	WELL	SI	04/01/2025	HE	017-07624	NORTH NAVAJO 5-34	SI

**General Comment:**

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on tank. Labeling is faded and needs replaced. Add capacity labeling		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 08/28/2025
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit needs updated to current operator		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Clean out dead weeds from around the base of the unit		
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:	Jugs of liquid around compressor need to be put into some kind of containment		
Corrective Action:	Comply with Rule 606		Date: 08/28/2025
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Compressor	# 1		corrective date
Comment:	Skid mounted gas powered booster compressor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Oilman 114		
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment: Meter shed on east side of VGS			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment: Gas scrubber, telemetry equipment at meter shed, chemical drum next to VGS			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: V6 Chevy motor			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment: Vertical gas separator inside red tank on west side of meter shed			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	400 BBLs	STEEL AST		38.615220,-102.554200
Comment: Crude oil tank has been removed					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	FIBERGLASS AST		38.615220,-102.554200
Comment: White tank with black stripe					
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 274906 Type: WELL API Number: 017-07624 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Producing. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404297252	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165275">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165275</a>
715202716	loaction photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165254">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165254</a>