

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2025

Submitted Date:

07/29/2025

Document Number:

715202713

FIELD INSPECTION FORM

Loc ID 321959 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 59925
 Name of Operator: MONUMENT GAS MARKETING INC
 Address: P O BOX 950
 City: MONUMENT State: CO Zip: 80132-

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Campbell, Randy	(719) 481-8029	rcampbell0614@adelphia.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285920	WELL	PR	01/31/2007	GW	017-07641	GLADYS COTRELL TRUST 2	PR

General Comment:

[SE Compliance Specialist Brian Welsh](#) conducted an audit and routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Dirt road through CRP		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks are peeling off and need replaced. Add capacity labeling		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 08/28/2025
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Tubing next to unit needs reomved from location		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 600px; height: 20px;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:				corrective date
Type:	Vertical Separator	# 1		
Comment:	Vertical gas separator inside berms on east side of tanks			
Corrective Action:				Date:
Type:	Ancillary equipment	# 5		
Comment:	Telemetry equipment at meter sheds, propane tank, solar powered cathodic rectifier, 2-gas scrubbers			
Corrective Action:				Date:
Type:	Deadman # & Marked	# 4		
Comment:				
Corrective Action:				Date:

Type: Prime Mover	# 1		
Comment:	350 Vortec Chevy Engine		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Stout 1-34		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 228		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	300 BBLs	STEEL AST		38.692000,-102.541440
Comment:	Corrected from Steel tanks to Fiberglass tanks for current inventory				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		38.692000,-102.541440
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	FIBERGLASS AST		38.692000,-102.541440

Comment:		
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 285920 Type: WELL API Number: 017-07641 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404297249	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165273
715202719	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165258