

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2025

Submitted Date:

07/24/2025

Document Number:

717900253

**FIELD INSPECTION FORM**

Loc ID 327554 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Nikki Graber		nikki.graber@state.co.us	
Jeremy Ferrin		jeremy.ferrin@state.co.us	
Kari Brown		kari.l.brown@state.co.us	

**General Comment:**

This is an environmental inspection for Location ID 327554 Webber 21-4 location. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Weeds present in Western open excavation.

Corrective Action: Comply with Rules 606 and 1002.f.(2).D.

Date: 08/07/2025

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment: This site has an open Remediation Project, but no spill present at time of inspection. There are two open excavations on site. Both are surrounded by orange construction fencing and contain groundwater.

Multiple Spills and Releases?

**Fencing/:**

Type

Comment: Open excavation to the East has inadequate fencing around excavation. Fencing is falling down. See photos.

Corrective Action: Rule 913.b(5)B.i. Operators will fence or cover open excavations to prevent access when sites are not attended.

Date: 08/07/2025

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 327554 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** Two onsite open excavations have groundwater. Neither are covered with a netting to deter wildlife.

Corrective Action: **Install wildlife screen per Rule 608.b.(7). If necessary contact CPW and/or USFWS.**

**Date:** 08/07/2025

**Comment:** Stormwater BMPs around and below the soil stockpile containing impacted material are inadequate.

**Corrective Action:** Manage waste in compliance with Rule 913.b.iv and ECMC Guidance 913.b.(5)B i-v. Prior to spill/remediation closure Operator will collect soil samples from underneath the observed soil stockpile area..

**Date:** 08/07/2025

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: This inspection is relation to the open Remediation Project at this site. Rem Project# 39423. Unlined contaminated soil stockpile remains on site.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p>This inspection is relation to the open Remediation Project at this site. Rem Project# 39423. Unlined contaminated soil stockpile remains on site. Operator states the material being stored on site is impacted in Form 27 Document # 404259905.</p> <p>Stock pile contains approximately 2 yards of contaminated soil surrounded by an uncompacted earthen berm and no liner.</p> <p>Two open excavations are on location. Both are approximately 10' x 15' x 6'. Both have orange construction fencing surrounding them, but the fencing at the Easternmost excavation is falling down on one side.</p> <p>Both have observable groundwater present and neither have any wildlife protection netting or other deterrent/BMPs.</p>	robinsotl	07/24/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404297316	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165351">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165351</a>
717900254	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165340">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7165340</a>