

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2025

Submitted Date:

08/05/2025

Document Number:

709100539

**FIELD INSPECTION FORM**

Loc ID 316908 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

6 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233118	WELL	PR	10/01/2023	OW	121-05140	DECKER B 1	EI
316908	LOCATION	AC			-	DECKER B-64S53W 18NWNW	EI

**General Comment:**

On August 1, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the DECKER B-64S53W/18NWNW location (Location ID: 316908), the Decker "B" 1 pit (Facility ID 117727), and the Decker B 1 well (API 05-121-05140).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type			
Comment:	Signage present at wellhead		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Emergency contact number faded from partially buried tank vessel and tank battery		
Corrective Action:	Comply with Rule 605.e		Date: 08/12/2025

<b>Good Housekeeping:</b>			
Type			
Comment:	Unused equipment observed on location / Comply with Rule 606		
Corrective Action:			Date:
Type			
Comment:	Noxious weeds observed onto oil and gas pad location and among pits		
Corrective Action:	Comply with Rule 1003.f.		Date: 08/08/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
	WELLHEAD		
Comment:	Hydrocarbons observed around the wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.		Date: 08/08/2025

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	No Rule 909.j. data on file		
Corrective Action:	Operator shall submit Rule 909.j data for Decker "B" 1 pit (Facility ID: 117727)		Date: 09/01/2025
Type:	#		
Comment:	Form 15 Pit Permit does not register current operator		
Corrective Action:	No pit permit on file under current Operator for Production Pit observed on location. Comply with rule 909.a.(1). Submit an eForm 15 Pit Permit Report to update ECMC records with current information and demonstrate compliance with Rules 908, 909, and 910, specifically Rule 909.b. Include Produced Water Quality Analyses data.		Date: 09/01/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Burrows present and observed in berms.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 09/01/2025
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 233118 Type: WELL API Number: 121-05140 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 316908 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100540	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175522">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175522</a>