

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2025

Submitted Date:

08/05/2025

Document Number:

709100537

FIELD INSPECTION FORM

Loc ID: 457751
Inspector Name: Heibel, Krystal
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 35080
Name of Operator: GRAND MESA OPERATING CO
Address: 1700 N WATERFRONT PKWY B600
City: WICHITA State: KS Zip: 67206

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Krystal Heibel		krystal.heibel@state.co.us	
,	1-316-633-6013	jcrombie@gmocks.com	All Inspections
BREWER, PHYLLIS		PBrewer@GMOCKS.com	REGULATORY
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457750	WELL	PR	07/17/2023	OW	121-11081	The Undeclared 1-7	EI
457751	LOCATION	AC			-	THE UNDEFEATED 1-7	EI

General Comment:

On August 1, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the The Undeclared location (Location ID: 457751) and The Undeclared 1-7 well (API 05-121-11081).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type			
Comment:	signage present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency contract number present		
Corrective Action:		Date:	

Good Housekeeping:

Type			
Comment:	Trash observed on location / Comply with Rule 606		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
Comment:	Hydrocarbons observed leaking from pumpjack onto concrete slab and onto soil.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:	09/01/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#			corrective date	
Comment:	No wildlife protection equipment (e.g. netting) installed at storage tank's secondary containment.				
Corrective Action:	Comply with Rule 902.b to install or repair wildlife protection equipment.			Date:	09/01/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS		
Comment:							
Corrective Action:						Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment:		Burrows present and observed in berms.				
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	09/01/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 457750 Type: WELL API Number: 121-11081 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 457751 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100538	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175521