

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/05/2025

Document Number:

715801302

**FIELD INSPECTION FORM**

Loc ID 317830 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 16 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240033	WELL	PR	09/11/1973	GW	123-07821	SUCKLA G UNIT 1	PR
464785	TANK BATTERY	AC	05/31/2019		-	Suckla G Unit 1 & Unit 2 battery	AC

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Faded, peeling hard to read and need to be updated		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/06/2024

<b>Emergency Contact Number:</b>			
Comment:			Date:
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Vegetation overgrown & dead around location & equipment.		
Corrective Action:	Comply with Rule 606	Date:	03/06/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	electric panel, meter box, transformers	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:	manifold	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	DCP Gas meter calibration record not current.	
Corrective Action:	Measure gas per Rule 430	Date: 07/06/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.100230,-104.898590
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: <span style="color:blue;">shares containment with crude tank</span>				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-08881
123-07821

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240033 Type: WELL API Number: 123-07821 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 464785 Type: TANK API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 8-5-2025 at approximately 1515 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 716400195 &amp; 715800802.                      Operator: KP Kauffman                      Location ID # 317830                      Well Name: Suckla G unit 1                      API # 05-123-076821                      County: Weld                      Weather: Claer                      Temperature: 105*                      Location: Dry                      While there, I observed a wellsite &amp; tank battery, PR at the time of the inspection. During this inspection, I observed the following compliance issues are delinquent:                      430 Gas Measurement: CA date 7-6-2024                      605.h tank labels/placards: CA date 8-6-2024                      606 housekeeping: CA 3-6-2025                      See attached photos.                      A follow up site inspection will be conducted to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/05/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801303	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175815">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175815</a>