

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/05/2025

Document Number:

715801304

FIELD INSPECTION FORM

Loc ID 318314 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241094	WELL	PR	01/01/2024	GW	123-08882	SUCKLA FARMS C 3	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well information is faded and not legible.		
Corrective Action:	Install/Replace sign to comply with Rule 605.g.	Date:	08/06/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type			
Comment:	vegetation throughout location needs to be removed per rule 606, CA date 8-12-2025		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	

Type: Ancillary equipment	# 1	
Comment:	Electric panel(shut off), meter box and transformers,	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 241094 Type: WELL API Number: 123-08882 Status: PR Insp. Status: PR

Producing Well

Comment: PR the electric panel is shut off.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 8-5-2025 at approximately 1550 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc# 716400189 Operator: KP Kauffman Location ID # 318314 Well Name: Suckla Farms C3 API # 05-123-08882 County: Weld Weather: Clear Temperature: 105* Location: Dry While there, I observed a wellsite, PR at the time of the inspection. During this inspection, I observed the following possible compliance issues: 605.g. Signs: CA date 8-6-2024 606 housekeeping : vegetation needs to be removed. See attached photos. A follow up site inspection will be conducted to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801306	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7175816