

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2025

Submitted Date:

07/30/2025

Document Number:

713400943

**FIELD INSPECTION FORM**

Loc ID 315008 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 17 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone | Email                        | Comment |
|-------------------|-------|------------------------------|---------|
| Katz, Aaron       |       | aaron.katz@state.co.us       |         |
| Kellerby, Shaun   |       | shaun.kellerby@state.co.us   |         |
| GAS, UTAH         |       | inspections@utahgascorp.com  |         |
| Koch, Benjamin    |       | bzkoch@blm.gov               |         |
| Haverkamp, Curtis |       | curtis.haverkamp@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 230087      | WELL | PR     | 02/01/2011  | GW         | 103-07746 | FEDERAL 22-1  | PR          |

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)

On 07/23/2025 at approximately 10:29 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-1 PAD at Location ID #315008 in Rio Blanco County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Inspected Facilities - Bradenhead test indicates possible lack of mechanical integrity/not in compliance with CECMC rules with a CA date of 08/30/2025
2. Inspected Facilities - Well lacks wellbore diagram/not in compliance with CECMC rules with a CA date of 08/30/2025
3. Stormwater - Berms on location need maintenance with a CA date of 08/14/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |                                     |  |       |
|----------------------|-------------------------------------|--|-------|
| <b>Signs/Marker:</b> |                                     |  |       |
| Type                 | WELLHEAD                            |  |       |
| Comment:             |                                     |  |       |
| Corrective Action:   |                                     |  | Date: |
| Type                 | TANK LABELS/PLACARDS                |  |       |
| Comment:             |                                     |  |       |
| Corrective Action:   |                                     |  | Date: |
| Type                 | BATTERY                             |  |       |
| Comment:             | <a href="#">Sign on meter house</a> |  |       |
| Corrective Action:   |                                     |  | Date: |
| Type                 | CONTAINERS                          |  |       |
| Comment:             | <a href="#">Chemical tank</a>       |  |       |
| Corrective Action:   |                                     |  | Date: |

|                           |                                  |  |             |
|---------------------------|----------------------------------|--|-------------|
| Emergency Contact Number: |                                  |  |             |
| Comment:                  | <a href="#">970-693-6021/911</a> |  |             |
| Corrective Action:        |                                  |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                           |  |  |                 |
|---------------------------|--|--|-----------------|
| <b>Equipment:</b>         |  |  | corrective date |
| Type: Gas Meter Run       | # 1  |  |                 |
| Comment:                  |  |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Bradenhead          | # 1  |  |                 |
| Comment:                  | <a href="#">No form of pressure monitoring equipment. Bradenhead valve is accessible</a> |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Ancillary equipment | # 1  |  |                 |
| Comment:                  | <a href="#">Chemical tank</a>  |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Bird Protectors     | # 1  |  |                 |

|                                   |   |       |  |
|-----------------------------------|---|-------|--|
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Horizontal Heated Separator | # 1                                     |       |  |
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Plunger Lift                | # 1                                     |       |  |
| Comment:                          | Well on plunger lift                    |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Ancillary equipment         | # 1                                     |       |  |
| Comment:                          | Flameless gas infrared catalytic heater |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Deadman # & Marked          | # 4                                     |       |  |
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |

**Tanks and Berms:**

| Contents           | #                                | Capacity | Type     | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|----------|---------|--------|
| PRODUCED WATER     | 1                                | OTHER    | Open Top |         |        |
| Comment:           | Tank not equipped with telemetry |          |          |         |        |
| Corrective Action: |                                  |          |          |         | Date:  |

**Paint**

|                  |            |  |
|------------------|------------|--|
| Condition        | Inadequate |  |
| Other (Content)  |            |  |
| Other (Capacity) | 30 bbls    |  |
| Other (Type)     |            |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 230087 Type: WELL API Number: 103-07746 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift

Well lacks wellbore diagram/not in compliance with CECMC rules

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17

Date: 08/30/2025

**BradenHead**

Date of Last Brhd Test: 05/29/2025 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 50 Fluid Type: NONE

End Surf Csg Pressure: 50

Comment: BH test in 2025 had a 0 psi differential between SC & PC.

08/30/2025

Bradenhead test indicates possible lack of mechanical integrity/not in compliance with CECMC rules

Corrective Action: Operator shall perform diagnostic testing on the well to demonstrate mechanical integrity. Submit results on a FORM 4 SUNDRY. Additionally contact CECMC Engineering Group to discuss observed compliance issue.

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                            |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|------------------------------------|
|                  |                 | Ditches                 |                       |  |                          |                                    |
| Ditches          |                 |                         |                       |  |                          |                                    |
| Compaction       |                 |                         |                       |  |                          | Light compaction                   |
| Berms            | Fail            |                         |                       |  |                          | Berms on location need maintenance |
|                  |                 | Compaction              |                       |  |                          | Light compaction                   |
|                  |                 | Berms                   |                       |  |                          |                                    |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          | Chemical tank containment          |

Comment: [1. Berms on location need maintenance](#)

Corrective Action: [Comply with CECMC Stormwater rules](#)

Date: 08/14/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <a href="#">Please refer to Inspected Facilities &amp; Stormwater for corrective actions.</a> | popejoyd | 07/30/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 404300665    | INSPECTION SUBMITTED              | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168685">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168685</a> |
| 713400944    | 713400943 Inspection-Audit Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168680">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7168680</a> |