

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2025

Submitted Date:

07/30/2025

Document Number:

716301283

**FIELD INSPECTION FORM**

Loc ID 333441 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name            | Phone        | Email                      | Comment                         |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 272706      | WELL | SI     | 06/01/2024  | CBM        | 071-08108 | TRIUMPH 13-10    | SI          |
| 287383      | PIT  | AC     | 10/13/2006  |            | -         | TRIUMPH 13-10    | AC          |
| 289129      | WELL | PR     | 05/19/2007  | CBM        | 071-09188 | TRIUMPH 13-10 TR | PR          |
| 301627      | PIT  |        | 02/19/2009  |            | -         | TRIUMPH 13-10TR  |             |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                      | #   |  |  | corrective date |
|---------------------------|-----|--|--|-----------------|
| Type: Ancillary equipment | # 2 |  |  |                 |
| Comment:                  |     |  |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Prime Mover         | # 2 |  |  |                 |
| Comment:                  |     |  |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Gas Meter Run       | # 2 |  |  |                 |
| Comment:                  |     | BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR. |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Vertical Separator  | # 2 |  |  |                 |
| Comment:                  |     |  |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Bradenhead          | # 2 |  |  |                 |
| Comment:                  |     | BOTH ARE ACCESSABLE  |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Progressive Cavity  | # 2 |  |  |                 |
| Comment:                  |     |  |  |                 |
| Corrective Action:        |     |  |  | Date:           |
| Type: Deadman # & Marked  | # 6 |  |  |                 |
| Comment:                  |     |  |  |                 |
| Corrective Action:        |     |  |  | Date:           |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 272706 Type: WELL API Number: 071-08108 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: WELL LAST PRODUCE MAY 2024

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/13/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 287383 Type: PIT API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 289129 Type: WELL API Number: 071-09188 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/13/2011 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301627 Type: PIT API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:   
 Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 287383 Lat: 37.269970 Long: -104.774800

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:   
 Corrective Action  Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment:   
 Corrective Action  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:   
 Corrective Action  Date: \_\_\_\_\_

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:   
 Corrective Action  Date: \_\_\_\_\_

Type: Produced Water Lined: YES Pit ID: 301627 Lat: 37.269790 Long: -104.775100

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: PHOTO 5: TR PRODUCED WATER PIT. THERE IS NO SYSTEM SET TO ALLOW WILDLIFE A WAY OUT OF LINED PIT.  
 Corrective Action COMPY WITH RULE 909.b. Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. (PROVIDE SOME WAY FOR WILDLIFE TO EXIT PIT). Date: 08/09/2025

**Fencing:**

Fencing Type: Other Fencing Condition: Adequate

Comment: BARBED WIRE  
 Corrective Action  Date: \_\_\_\_\_

|                                   |   |                               |
|-----------------------------------|---|-------------------------------|
| <b>Netting:</b>                   |   |                               |
| Netting Type:                     | Netting Condition:                        |                               |
| Comment:                          | <input style="width: 100%;" type="text"/> |                               |
| Corrective Action                 | <input style="width: 100%;" type="text"/> |                               |
| Anchor Trench Present: <u>YES</u> | Oil Accumulation: <u>NO</u>               | 2+ feet Freeboard: <u>YES</u> |
| Comment:                          | <input style="width: 100%;" type="text"/> |                               |
| Corrective Action                 | <input style="width: 100%;" type="text"/> |                               |
|                                   |   | Date:                         |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404299113    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7167218">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7167218</a> |
| 716301286    | INSP. PHOTOS         | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7167201">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7167201</a> |