

Final Reclamation and Stormwater Inspection

July 30, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 305233

Well Name: MATTORANO #42-9

Inspection Document #: 718600834

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 1. Looking west down the access road. It appears a new access road unrelated to oil and gas has been constructed partially overlapping the original access road.



Photo 2. Approximately 200 ft in from the gate a new road is present. It appears this road is being used to access outbuildings on the property.



Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 3. Picture taken at the junction of the new and old access road looking west down the road towards the tank battery. Vegetation on the access road is primarily undesirable weed kochia.



Photo 4. This portion of access road appears to be unused and has a relatively large amount of gravel.



Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 5. Looking west across the former tank battery location. No oil and gas equipment remains. At the time of inspection vegetation is primarily undesirable weed kochia and list C noxious weed cheatgrass.



Photo 6. Looking east down the south side of the tank battery. Illustrating difference in vegetation between the tank battery and interim reclamation area (tank battery on the left side of the red line). The interim reclamation area on the southwest side of the location appears to have established perennial vegetation.

Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 7. Looking south from the tank battery towards the well location. The access road and wellbore area are partially located in an area with low vegetation coverage. Undesirable weeds such as kochia and list C noxious weed cheatgrass are present in this area. Desirable perennial grass species area also present to the southwest.



Photo 8. Looking west from the wellbore area. See photo 7 comments.



Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 9. Looking south from the wellbore area. See photo 7 comments.



Photo 10. Looking east from the wellbore area. See photo 7 comments.

Inspection Photos
Location Name: MATTORANO #42-9
Location ID: 305233



Photo 11. Reference vegetation to the south of well location.