

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256




Photo # 8402 From entrance to location

Photo # 8403 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8404 Location



Photo # 8405 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8406 Location



Photo # 8407 Debris

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8408 Debris



Photo # 8409 Debris

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8410 Improper storage of flammable liquids in shed/shed not in compliance with CECMC Rule 610

Photo # 8411 Improper storage of flammable liquids in shed/shed not in compliance with CECMC Rule 610

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8412 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 8413 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8414 Possible tank failure/tank appears to lack integrity



Photo # 8415 Possible tank failure/tank appears to lack integrity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8416 Open ended load line



Photo # 8417 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8418 Open ended load line



Photo # 8419 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8420 Open ended load line



Photo # 8421 Open ended piping/load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8422 Open ended load line



Photo # 8423 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8424 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 8425 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 13-33 Tank Pad

Location ID: 439256



Photo # 8426 Dead bird in secondary containment



Photo # 8427 Dead bird in secondary containment