

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Photo # 1085 Entrance to location




Photo # 1098 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Aug 1, 2025 at 9:11:08 AM  
+39.813164, -108.768260 ±3.04m  
Rangely



Aug 1, 2025 at 9:15:31 AM  
+39.813172, -108.768268 ±6.74m  
Rangely

Photo # 1086 Location

Photo # 1092 Wellhead sign lacks required information

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Photo # 1095 Location



Photo # 1131 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Photo # 1132 NW corner of location



Photo # 1133 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Photo # 1134 SE corner of location



Photo # 1110 Open ended piping/wildlife hazard/available for entry by wildlife

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



**Photo # 1118 Open ended piping/wildlife hazard/available for entry by wildlife**



**Photo # 1119 Chemical tank lacks required labeling**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



**Photo # 1122 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**



**Photo # 1123 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



**Photo # 1124 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**

**Photo # 1125 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



**Photo # 1126 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**



**Photo # 1127 Tunnel erosion on location, additionally is a wildlife hazard/personnel safety hazard**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #18 PAD

Location ID: 314972

Date: 08/1/2025



Photo # 1128 Debris on location



Photo # 1130 Debris on location