

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2025

Submitted Date:

07/31/2025

Document Number:

712300170

**FIELD INSPECTION FORM**

Loc ID 436485 Inspector Name: Maxwell, Logan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10421  
Name of Operator: PETROLEUM RESOURCE MANAGEMENT CORP  
Address: 1110 SOUTH VINE STREET  
City: DENVER State: CO Zip: 80210

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		aaron.trujillo@state.co.us	
		emily.waldron@state.co.us	
		hhill@fieldinghillllc.com	
		chris@fieldinghillllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436485	LOCATION	AC			-	WPU-36 1	RI

**General Comment:**

On 07/02/2025, Reclamation Specialist Maxwell and Reclamation Work Lead Trujillo conducted a reclamation inspection at PRM's WPU-36-1 #H2, Location #436485 in Moffat County, Colorado.

This inspection is a follow-up to #712300102 to document compliance with the following corrective actions:  
- Weed Management

This inspection is also in response to Resolution Nos. 403908355 and 403983539 stating corrective actions have been completed.

The following compliance issues were observed during this inspection:  
-Weed Management

Refer to the "Location," and "Reclamation," sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	At the time of this inspection, unused rock material was observed stockpiled near the entrance of the Location.		
Corrective Action:	Comply with Rule 606.	Date:	
Type	UNUSED EQUIPMENT		
Comment:	It was observed in this inspection, that there was various trash/debris observed on the west end of the Location. See Photos 5-6.		
Corrective Action:	Comply with Rule 606.	Date:	08/08/2025
Type	WEEDS		
Comment:	<p>Previous inspections observed Undesirable Plant Species (Bull thistle, Canada thistle, Houndstongue) established on the Location, including the cut and fill slopes. Inspections required Operator to comply with Rule 606.c and 1003.f by 10/18/2023.</p> <p>It was observed in this inspection that Noxious Weeds have persisted on the Location; it was apparent efforts to control weeds had been applied but have been insufficient throughout the entire Location. New noxious weed infestations include field bindweed in addition to the previous species seen.</p>		
Corrective Action:	<p>CA per inspection #696205338: Comply with Rules 606.c and 1003.f.</p> <p>Comply with Rules 606.c and 1003.f. Keep Location free of all Undesirable Plant Species. Ongoing weed monitoring/management required until Location receives a passing Final Reclamation Inspection.</p>	Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 436485 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_ Fail

Comment With use of a sUAS, it was observed that approximately 2,009 CY of topsoil was salvaged and stored on the North end of the Location. The areas of disturbance where topsoil was required to be salvaged is 4.34 acres. At a minimum of 6", at least 3,497 cubic yards of topsoil should have been salvaged and stored. Based on documents, Operator identified that 12 inches of topsoil existed. 6,995 cubic yards should have been salvaged based on 12 inches. Stockpile is missing between 1,488 (@6") to 4,986 (@12") cubic yards of topsoil material.  
  
A source of topsoil for importation has been identified and upon the approval of the OGD, shall be brought into the Location and stored for future reclamation purposes.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ F \_\_\_\_\_

Comment

Remediation Project #36128 remains active at the time of the inspection.  
 It is noted that Operator submitted Docket #240800186 requesting a 502 variance to Rule 1003.b for delayed Operations; the variance request is currently pending Hearings and a decision by the Commission. Be advised- a submission for a variance request does not guarantee approval; corrective action(s) and action date(s) would remain applicable until resolved if request is denied. Additionally, approval of a variance does not absolve the Operator from possible enforcement action due to past non-compliance of the reclamation rules.

Corrective Action

\_\_\_\_\_

Date

\_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

\_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404302275	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170293">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170293</a>
712300187	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170272">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170272</a>