

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/31/2025

Document Number:

707801727

## FIELD INSPECTION FORM

 Loc ID 312779 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 ECMC Operator Number: 45898  
 Name of Operator: KAISER-FRANCIS OIL COMPANY  
 Address: P O BOX 21468  
 City: TULSA State: OK Zip: 74121
**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Opfer, Christina	(918) 491-4468	christinao@kfoc.net	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222379	WELL	PR	01/01/2024	GW	081-05370	GOVT-WINDER 1	PR

**General Comment:****ECMC Inspection Report Summary**

On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Kaiser Francis Government Winder 1, at Location # 312779 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Well signage lacks information.
2. Belt guard is missing

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

<b>Location</b>			
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well signage lacks information.		
Corrective Action:	Provide proper signage Within 60 days after a new Well is Completed, including each Well on a Multi-Well Site, or an existing sign is replaced or modified, a permanent sign will be conspicuously located at the wellhead and will identify: A. The Well name; B. The API number; and C. Its legal location, including the quarter/quarter section. When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: A. Name of the Operator; B. Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); and D. The public road used to access the Well.		Date: 09/01/2025
Emergency Contact Number:			
Comment:	<input type="text" value="(405) 262-5511"/>		Date: _____
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Belt guard is missing.		
Corrective Action:	Install proper safty equipment/ Eliminate possibility of wildlife or personnel from being harmed from equipment.		Date: 09/01/2025
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Ancillary equipment # 1			corrective date
Comment: 500 gallon methanol tank in metal containemt			
Corrective Action:			Date:
Type: Pump Jack # 1			
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No NO			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222379 Type: WELL API Number: 081-05370 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No storm water BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404302390	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170477">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170477</a>
707801731	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170447">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170447</a>