

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2025

Submitted Date:

07/31/2025

Document Number:

707801729

FIELD INSPECTION FORM

Loc ID 312984 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

11 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10673

Name of Operator: GADECO LLC

Address: 7535 EAST HAMPDEN AVE STE 400

City: DENVER State: CO Zip: 80231

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, COGCC		dnr_cogccengineering@state.co.us	engineering
General, contact		argaliexplorationcompany@gmail.com	all inspections
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223168	WELL	PR	12/01/2023	GW	081-06530	SCHIECK 11-31	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday 7/15/2024, I, Inspector Scott Ramsey, conducted a routine inspection on site at Argali Exploration Schieck 11-31, at Location # 312984 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Random debris
2. Weeds throughout location and access road.
3. Tank thief hatch is unlatched.
4. Open line on tank.
5. Methanol tank lacks proper labeling.
6. Tank labeling is lacking information.
7. Lack of battery signage.
8. Containment is insufficient.
9. No form 15 on file for pit. Pit fencing is open to wildlife. Also some unknown fluid in the bottom of pit.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank labeling is lacking information.		
Corrective Action:	Provide proper labeling	Date:	09/01/2025
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	09/01/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol tank lacks proper labeling.		
Corrective Action:	Provide proper signage	Date:	08/14/2025

Emergency Contact Number:			
Comment:	970-629-1906		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	08/14/2025
Type	OTHER		
Comment:	Tank thief hatch is unlatched.		
Corrective Action:	Latch thief hatch and eliminate venting	Date:	08/14/2025
Type	WEEDS		
Comment:	Weeds throughout location and access road.		
Corrective Action:	Remove weeds	Date:	08/14/2025
Type	OTHER		
Comment:	Open lines on tank.		
Corrective Action:	Repair line going into tank and cap load lines.	Date:	08/14/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment: Containment is insufficient.				
Corrective Action: Maintain secondary containment				Date: <u>09/01/2025</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berm				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment: Containment is insufficient.				
Corrective Action: Maintain secondary containment				Date: <u>09/01/2025</u>

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 223168 Type: WELL API Number: 081-06530 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No form 15 on file for pit. Pit fencing is open to wildlife. Also some unknown fluid in the bottom of pit.

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908

Date: 08/21/2025

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
Reference Point:	Other:	Length:	Width:	

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____
 Corrective _____

Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Inadequate

Comment: Pit fencing is open to wildlife.
 Corrective Eliminate possibility of wildlife or personnel from falling into open holes.

Date: 09/01/2025

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____
 Corrective _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____
 Corrective _____

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404302392	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170479
707801733	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170449