

Inspection Photos

08/5/2025

Operator: PUCKETT LAND COMPANY - 10341

Location ID: 322527

Inspection Doc: 718100705

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 1: Photos 1-2 taken from the central areas of the Location. Photos provide an overview of the Location from northeast, southeast, southwest to northwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 3: Photo taken from the north end of the Location, facing northwest. Photo example showing Noxious weed establishment (Musk thistle) observed throughout the Location. Though previous weed management efforts appear to have been performed, work was insufficient; weeds remain viable throughout the Location, and have reached seed-head maturity. Additional and ongoing weed management efforts required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 4: Photo taken from the eastern areas of the Location, facing southwest. Photo shows the starting point for the “Disturbance area” (Location) transect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 5: Photo taken from the 50th point of the Disturbance Area transect; facing north and south respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 6: Photo taken from the 50th point of the Disturbance Area transect. Photo shows surface of the Location, including soils and vegetation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 7: Photo taken from the western areas of the Location, facing northeast. Photo shows the end point for the Disturbance area transect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 8: Photo taken from the adjacent reference area, facing west. Photo shows the starting point for the Reference Area transect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 9: Photo taken from the 50th point of the Reference Area transect; facing north and south respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 10: Photo taken from the 50th point of the Reference Area transect. Photo shows surface of the Reference areas, including soils and vegetation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 11: Photo taken from the adjacent reference area, facing east. Photo shows the end point for the Reference Area transect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 12: Photos 12-13 taken from the O&G access road leading to the Location. Photos examples showing that the Road has not been reclaimed; access road did not exist prior to the Location, and was constructed for the purpose of accessing an Oil and Gas Location and is therefore subject to 1004 Reclamation Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 13: See comments under photo 12. Yellow arrow shows sign frame for the Location remaining at the access road (see photo 14).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY - 10341

Location ID: 322527



Photo 14: Continued from photo 13. Photo shows sign frame for the Location remaining at the access road



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources