

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/07/2025

Submitted Date:

08/07/2025

Document Number:

715801319

FIELD INSPECTION FORM

Loc ID 318222 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 18 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240907	WELL	SI	01/01/2025	OW	123-08695	MARTIN T. HART F UNIT 1	SI

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	overgrown vegetation throughout location need to be removed.		
Corrective Action:	Comply with Rue 606	Date:	10/27/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Gas Meter Run	# 1		
Comment:	Meter not calibrated annually.		
Corrective Action:	Comply with Rule 430.	Date:	03/27/2025
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 2	
Comment:	Manifold	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Automation, electric panel, meter box & transformers	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	electric motor	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:	it appears the earthen berm surrounding the seperator is not well maintained & over run with vegetation.	
Corrective Action:	Comply with Rule 603.o	Date: 12/27/2024
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	shares containment with crude tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.104900,-104.884400
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: Earthen berm surrounding the tanks is not well maintained & over run with vegetation.				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-07443
123-10147
123-08695
123-09127
123-10148

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240907 Type: WELL API Number: 123-08695 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI since 12-24-2024

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary: On Wednesday 8-6-2025 at approximately 1120 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 714201704 & 715800806. Operator: KP Kauffman Location ID # 318222 Well Name: Martin T. Hart F Unit 1 API # 05-123-08695 County: Weld Weather: Partly Cloudy Temperature: 86* Location: Dry While there, I observed a wellsite & tank battery, SI at the time of the inspection. During this inspection, I observed the following compliance issues are delinquent: 606 housekeeping: CA 10-27-2024 603.o Berms: CA date 12-27-2024 430 Gas Measurement: CA date 7-6-2024 Any corrective actions from previous Inspections that have not been addressed are still applicable See attached photos. A follow up site inspection will be conducted to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/07/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801320	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7178361