

Inspection Photos

08/5/2025

Operator: QB ENERGY OPERATING LLC -
10844

Location ID: 335842

Inspection Doc: 718100714

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 1: Photos 1-2 taken from the working pad surface on the northwest end of the Location. Photos provide an overview of the Location from northeast, east, south to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 3: Photo left taken from interim areas on the north end of the Location, facing southwest; photo right taken from the interim areas on the south end of the Location, facing southwest. Photo examples showing interim areas appear to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 4: Photo taken from the interim areas on the north end of the Location, facing north. Photo example showing areas where topsoil is scarce, or does not appear to have been replaced.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 5: Photo example showing weed management efforts on the Location are evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 6: Photos taken from the edge of the working pad surface. Photos examples showing the fence on the Location is in disrepair. Maintenance required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 7: Photo taken from the interim areas on the north end of the Location, facing east. Photo examples showing fencing materials/debris observed within interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 8: Photo taken from the stormwater outlet on the north end of the working pad surface. Photo example showing the fence on Location in disrepair. Maintenance required. Photo also shows erosion degradation at the BMP is becoming evident. Maintenance advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 9: Photo taken from the northeast end of the working pad surface. Photo example showing an anchor missing required marking.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 10: Photo taken from the well string, facing northeast. Photo shows solar panels on the Location. Equipment appears to be damaged. Unclear if equipment is still in use however various parts associated with the equipment is spread around near the wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 11: Photos 11-14 examples showing various trash, debris and/or unused equipment on the Location. Photos taken from the separator equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 12: Photos taken from the tank battery facility. See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 13: Photo taken from the north end of the tank battery. See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 14: Photos taken from the valve can to the north of the battery facility. See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPE

Location ID: 335



Photo 15: Photos taken from the battery facility. Photos show lines at tanks missing cap/plug. Photo left also shows fluids spilled within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 16: Photos 16-17 taken from the tank battery facility. Photo shows the metal berm has become separated.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 17: Photo shows tear observed within liner at the tank battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 18: Photo taken from the 95 bbl tank, facing northeast. Photo shows open-ended pipe at tank. Wildlife protection BMPs missing at pipe.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 19: Continued from photo 18. Damage evident at the containment BMP. Unclear if BMP remains sufficiently impervious to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC - 10844

Location ID: 335842



Photo 20: Photo example of signage on the Location with the incorrect Operator listed. Signage at wells/tanks/battery require updating.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources