

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9123 From entrance to location



Photo # 9124 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9125 Location



Photo # 9126 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9127 Location



Photo # 9128 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9129 Location



Photo # 9130 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9131 PRV vent lines do not comply with CECMC pressure safety device rules




Photo # 9132 PRV vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Aug 7, 2025 at 11:57:20 AM
+39.481744,-108.132349



Aug 7, 2025 at 11:57:25 AM
+39.481744,-108.132349

Photo # 9133 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 9134 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CS_Starkey

Facility ID: 464837



Photo # 9135 Open ended load line



Photo # 9136 Staining near compressor