

Inspection Photos

August 6th, 2025

Operator: Hilcorp Energy Company

Location ID: 306932

Inspection Document #: 714002373

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

August 6, 2025
287° W




Photo 1. View of the project area taken from the access point facing center.

Inspection Photos
Location Name: Ute 34-10 101R
Location ID: 306932



Photo 2. Drone photo of previous active gully erosion area which has been collapsed, filled in and reseeded (evidence of germinating desirable species were observed). Smaller slumping, and erosion observed on the furthest downslope section (red arrow).



Photo 3. Ground view of collapsed gully erosion and reseeded area.



Inspection Photos
Location Name: Ute 34-10 101R
Location ID: 306932



Photo 5. Drone photo showing extent of active spill.

Inspection Photos
Location Name: Ute 34-10 101R
Location ID: 306932

