

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad

Location ID: 323862



Photo # 7893 From entrance to location



Photo # 7894 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad

Location ID: 323862



Aug 5, 2025 at 10:25:15 AM
+39.457231,-108.092950



Aug 5, 2025 at 10:26:17 AM
+39.457116,-108.092822

Photo # 7895 Location

Photo # 7896 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad

Location ID: 323862



Photo # 7897 Location



Photo # 7898 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad

Location ID: 323862



Photo # 7899 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7900 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC OXY USA INC MV 45-10 Pad

Location ID: 323862



Photo # 7901 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 7902 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules